## ABSTRACT OF THE DISCLOSURE

A brushless motor has a stator, a rotor and a circuit board for controlling rotation of the rotor.

The stator has iron cores and coils wound around the iron cores. Switching elements for turning on and off electric power to be supplied to the coils for the stator are mounted to the circuit board. A heat-radiating member is fixed to the iron cores.